PRINT DATE: 04/11/98 PAGE: 1

#### FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL HARDWARE NUMBER: M5-688-0111 -X

SUBSYSTEM NAME: ISS DOCKING SYSTEM

REVISION: 0

02/27/98

#### **PART DATA**

PART NAME **VENDOR NAME**  PART NUMBER VENDOR NUMBER

LRU

:PANEL A6A3

V828-730150

SRU

:FUSE

MC454-0018-0300

#### EXTENDED DESCRIPTION OF PART UNDER ANALYSIS:

FUSE, PLUG-IN, 3 AMP - PFCU "FIRE" POWER CIRCUIT.

REFERENCE DESIGNATORS:

36V73A7A3F3 36V73A7A3F4 36V73A7A3F5

36V73A7A3F11

QUANTITY OF LIKE ITEMS: 4

FOUR

#### **FUNCTION:**

PROVIDE OVERLOAD PROTECTION TO THE ORBITER CONTROL BUSES (CA1, AB2) OR ESSENTIAL BUSES (MN A - ESS3AB, MN B - ESS1BC) FROM THE PFCU "FIRE" POWER CIRCUIT.

REFERENCE DOCUMENTS:

1) VS70-953103, INTEGRATED SCHEMATIC - 63PA, PECU

POWER DISTRIBUTION CONTROL CIRCUIT

PRINT DATE: 04/11/98 PAGE 2

FAILURE MODES EFFECTS ANALYSIS FMEA -- NON-CIL FAILURE MODE

NUMBER: M5-6\$5-0111-01

REVISION#: 0

02/27/98

SUBSYSTEM NAME: 188 DOCKING SYSTEM

LRU: PANEL A6A3 ITEM NAME: FUSE **CRITICALITY OF THIS** FAILURE MODE: 1R3

FAILURE MODE:

FAILS OPEN

MISSION PHASE: OO ON-ORBIT

VEHICLE/PAYLOAD/KIT EFFECTIVITY:

103 DISCOVERY

104 ATLANTIS

105 ENDEAVOUR

CAUSE:

A) STRUCTURAL FAILURE, B) CONTAMINATION, C) VIBRATION, D) MECHANICAL SHOCK, E) PROCESSING ANOMALY, F) THERMAL STRESS

CRITICALITY 1/1 DURING INTACT ABORT ONLY? NO

CRITICALITY 1R2 DURING INTACT ABORT ONLY (AVIONICS ONLY)? NO

REDUNDANCY SCREEN

A) PASS

B) N/A

C) PASS

PASS/FAIL RATIONALE:

Αŀ

B)

PYROTECHNIC SEPARATION CLASSIFIÉD AS STANDBY REDUNDANCY

C)

CORRECTING ACTION: NONE

CORRECTING ACTION DESCRIPTION:

DESIGN FAULT TOLERANCE: REDUNDANT PYROTECHNIC SEPARATION CIRCUIT

REMAINS OPERATIONAL.

# FAILURE MODES EFFECTS ANALYSIS (FMEA) -- NON-CIL FAILURE MODE NUMBER: M5-8SS-0111-01

#### - FAILURE EFFECTS -

#### (A) SUBSYSTEM:

LOSS OF REDUNDANCY TO PROVIDE CONTROL LOGIC POWER TO ENERGIZE PECU BUS 1 (OR 2) THROUGH RPCS IN MPCA 1.

#### (B) INTERFACING SUBSYSTEM(8):

DEGRADED REDUNDANCY FOR PYROTECHNIC SEPARATION CAPABILITY. LOSS OF ONE OF TWO FIRE CURRENT PATHS TO THE SEPARATION PYROBOLTS.

#### (C) MISSION:

FIRST FAILURE - NO EFFECT

### (D) CREW, VEHICLE, AND ELEMENT(S):

FIRST FAILURE - NO EFFECT

### (E) FUNCTIONAL CRITICALITY EFFECTS:

POSSIBLE LOSS OF CREW/VEHICLE AFTER FOUR FAILURES:

- 1) FUSE OPENS DEGRADED REDUNDANCY FOR PYROTECHNIC SEPARATION.
- 2) ONE OF THE TWELVE HOOKS FAILS TO OPEN (REF. FMEA M8-ISS-BM001-04). LOSS OF NOMINAL UNDOCKING CAPABILITY.
- 3) FUSE IN THE PARALLEL CIRCUIT FAILS OPEN.
- 4) SWITCH IN THE REDUNDANT CIRCUIT FAILS OPEN LOSS OF PECU "FIRE" CAPABILITY. LOSS OF NOMINAL AND PYROTECHNIC UNDOCKING CAPABILITY.

## DESIGN CRITICALITY (PRIOR TO DOWNGRADE, DESCRIBED IN (F)):

## (F) RATIONALE FOR CRITICALITY DOWNGRADE:

ALTHOUGH THE CRITICALITY REMAINS UNCHANGED AFTER WORKAROUNDS CONSIDERATION (ALLOWED PER CR \$050107W), ADDITIONAL FAULT TOLERANCE IS PROVIDED TO THE SYSTEM.

AFTER THE FOURTH FAILURE, THE CREW WOULD PERFORM EVA TO REMOVE 96 BOLTS FROM THE DOCKING BASE TO CIRCUMVENT THE WORST CASE "DESIGN CRITICALITY" EFFECT. IF UNABLE TO PERFORM EVA (FIFTH FAILURE), POSSIBLE LOSS OF CREW/VEHICLE DUE TO LOSS OF ALL UNDOCKING CAPABILITY.

PAGE: 4 PRINT DATE: 04/11/98

## FAILURE MODES EFFECTS ANALYSIS (FMEA) — NON-CIL FAILURE MODE NUMBER: M5-6SS-0111-01

#### - TIME FRAME -

TIME FROM FAILURE TO CRITICAL EFFECT: DAYS

TIME FROM FAILURE OCCURRENCE TO DETECTION: MINUTES

TIME FROM DETECTION TO COMPLETED CORRECTING ACTION: HOURS

IS TIME REQUIRED TO IMPLEMENT CORRECTING ACTION LESS THAN TIME TO EFFECT? YES

RATIONALE FOR TIME TO CORRECTING ACTION VS TIME TO EFFECT:
DESIGN FAULT TOLERANCE: REDUNDANT PYROTECHNIC SEPARATION CIRCUIT REMAINS
OPERATIONAL. AFTER THE THIRD FAILURE, THE CREW CAN PERFORM PYROTECHNIC
SEPARATION TO UNDOCK.

HAZARD REPORT NUMBER(\$): ORBI 401

HAZARD(S) DESCRIPTION:

INABILITY TO SAFELY SEPARATE ORBITER FROM A MATERIAL ELEMENT.

#### - APPROVALS -

SS&PAE

: T. K. KIMURA

DESIGN ENGINEERING

: C. J. ARROYO